## PORSF 11.3.18.1 V4



NPDES #1300 Oily Discharge General Permit Discharge Monitoring Report

of following month to: Oregon DEQ 2020 SW 4th Avenue, Suite 40

Submit report monthly by

2020 SW 4th Avenue, Suite 4 Portland, Oregon 972(1)

Legal Name: KINDER MORGAN LIQUID TERMINALS LLC

Common Name: LINNTON TERMINAL

Facility Location: 11400 NW ST HELENS RD , PORTLAND

Site/File ID #: 32300 County: MULTNOMAH

Month/Year /1/4 2007

	٨.	donitoring for Oil	AWater Separator TAN	- 3034		
Day	Oil and Grease (mg/L)	Visible Sheen	Ethanol and/or MBTE	Flow  Daily estimate, when discharging		
	Frequency varies, see permit	Daily, visual observation	Quarterly grab sample, if present on site and in bulk			
Limit	10 mg/L monthly, 15 mg/L daily max.	No visible sheen at any time	No limit	No limit		
2 3						
4 5						
7	* /					
9		)				
11		00				
13 14 15		JAM				
16	115					
18						
20 21 22						
23 24						
25 26 27						
28 29						
30 31 -						
Total Max.						
Average						



See Reverse Side for Additional Monitoring and Signature Block

## Stormwater Monitoring

Only for facilities required to have NPDES permits for stormwater, per 40 CFR 122.26 Monitoring required for each point identified in the Stormwater Pollution Control Plan

Day	Visible Sheen	Floating Solids (associated with industry)	Total Copper (mg/L)	Total Lead (mg/L)	Total Zinc (mg/L)	pH (S.U.)	Total Suspended Solids (mg/L)
	Daily when discharging, visual observation	Once per month when discharging	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample
Limit	No visible sheen	No visible discharge*	0.1 mg/L*	0.4 mg/L*	0.6 mg/l.*	Within 6.0 to 9.0	130 mg/L*
1	8	1					
2							
3							
4			,				
5	******						
6							-
7							
8							
9							<u></u>
11							
12							·
13							
1.7							<u> </u>
1.5					-	-	<del> </del>
16	<del></del>	<del></del>					<del> </del>
17							<del></del>
18						-	
19							<del> </del>
20						<u> </u>	
21				· · · · · · · · · · · · · · · · · · ·		1	
22							
23							
24	<del></del>						
25					1		T
26		······································					
27							
28	B 10 Park Landson						
29				· -			
30							
31							
Total							
Max.			······································				
Average							

<sup>\*</sup>These are benchmarks, not effluent limits. If benchmarks are exceeded, review/possible revision of Stormwater plan is required. See permit for more details.

## Signature Requirement

I certify, under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing violations.

Signature of Responsible Official:	
Name and Title (Please Print): Tenker ( January Field Schedules	
Date of Signature: 7-3/-07 Telephone: 503 220 /276	